

YOUR HEALTH IS PRICELESS!

HAND AIR CONTROLS THE QUALITY OF THE AIR YOU BREATHE.

CHANGE THE AIR AT THE RIGHT TIME! (... AND FOR THE TIME NEEDED)

REDUCE
THE PRESENCE OF VIRUSES
PREVENT
WASTING ENERGY.







TECHNICAL SPECIFICATIONS:

CO2 measurements

Principle/sensor PAS

Measurement range 400 to 5,000 ppm

Uncertaintly ± (5% reading + 40) ppm

Resolution 1 ppm



